








GND at 2nd and 6th grad.



DC Voltage readings key on motor stalled



Lower trace at coil neg. taken at ICU pin 16 in all photos

